STATE OF WASHINGTON TO: JIM BROWN

ARTMENT OF COLOGY

DANIEL J. EVANS

GOVERNOR

Clympia, Washington 98504

February 28, 1972

Alaskan Copper Works P.O. Box 3546 Seattle, Washington 98124

### Gentlemen:

Enclosed is Waste Discharge Permit Number 3967, which has been issued in accordance with RCW 90.48.

We commend you for accepting your responsibility to prevent pollution by installing and maintaining the waste disposal facilities necessary to qualify for this permit.

Sincerely,

R. Verry Bollen
Assistant Director
Office of Operations

RJB:av

Enclosure

## STATE OF WASHINGTON DEPARTMENT OF ECOLOGY OLYMPIA, WASHINGTON

In accordance with Chapter 90.48 RCW, and Chapter 372-24 W.A.C. A WASTE DISCHARGE PERMIT is issued to:

Permit No. 3967

Date of Issue February 28, 1972

Date of Expiration February 28, 1977

Alaskan Copper Works (13011) P.O. Box 3546 Seattle, Washington 98124

6th Avenue South Plant

Waste from the permittee's industrial operation located at 3200 - 6th Avenue So., Seattle, not exceeding 20,000 gallons per day, may be discharged to the Municipality of Metropolitan Seattle sewerage system at the following point of discharge: 3200 6th Avenue South, Seattle.

Said discharge is authorized subject to the following conditions:

- 1. The word "waste" in the above statement refers to the total volume of cooling and contaminated waters to be discharged to the sanitary sewer.
- 2. Chemical cleaning, descaling and film developing processes are to be operated in a manner that will prevent excessive loss of chemicals to the sanitary sewer. These shall include:
  - A. Suspend treated parts above chemical solutions or drip pans for a reasonable time to minimize drag out.
  - B. Collect spent chemical solutions for reprocessing or disposal in a manner that will prevent their entry into waters of the state.
- 3. Rinsewaters from the X-ray film developing process and from the descaling process shall be periodically monitored and treated, as necessary, to ensure that the combined effluent to the sanitary sewer shall meet the following requirements:
  - A. Have a pH above 5.5.
  - B. Contain less than 6.0 parts per million chromium.
  - C. Contain less than 3.0 parts per million copper.
  - D. Contain less than 6.0 parts per million nickel.
  - E. Contain less than 0.1 parts per million silver.
  - F. Contain less than 100 parts per million total oils.

|         | _ |
|---------|---|
| Page    | 2 |
| A CAP C | - |

Permit No. 3967

Date of Issue February 28, 1972

Alaskan Copper Works Seattle, Washington

Date of Expiration February 28, 1977

4. A rinse water sump maintenance schedule, providing for regular inspection and periodic clean-out and replacement of limestone shall be submitted to the Department of Reology for approval. A copy of this schedule shall be posted near the sump and shall be available for on-site review by the Department. The schedule shall include:

- A. pH of effluent record each working day.
- B. Chromium concentration record monthly (analyze at least once a month).
- C. Complete analysis in accordance with Condition 3 record semiannually (analyze at least once every six months).
- D. Date of last clean out of sludge and replacement of limestone.
- 5. Contaminated waters shall not be discharged to the storm sewer.
- 6. Waste solvents, spent acid and alkaline cleaning solutions, chemical sludges, scrap metal and other solid waste material shall be collected for reprocessing or disposal in a manner that will prevent their entry into waters of the state.
- 7. Sanitary sewage is to be discharged into the sanitary sewer system.
- 8. All requirements and ordinances of the city pertaining to the discharge of wastes into the city sewer system are hereby made a condition of this permit.
- 9. In the event the permittee is temporarily unable to comply with any of the above conditions of this permit, due to breakdown of equipment or other cause, the permittee is to immediately notify this department. This report is to include pertinent information as to the cause and what steps are being taken to correct the problem and prevent its recurrence.

This permit does not allow the discharge of wastes other than those mentioned herein. A new application shall be submitted whenever a change in the waste to be discharged is anticipated.

This permit is subject to termination if the department finds: (1) That it was produced by misrepresentation of any material fact or by lack of full disclosure in the application; (2) That there has been a violation of the conditions thereof; (3) That a material change in quantity or type of waste disposal exists.

In the event that a material change in the conditions of the state waters utilized creates a dangerous degree of pollution, the department may specify additional conditions to this permit.

Page 3

Permit No. 3967

Date of Issue February 28, 1972

Alaskan Copper Works Seattle, Washington

Date of Expiration February 28, 1977

Nothing in this permit shall be construed as excusing the permittee from compliance with any applicable federal, state, or local statutes, ordinances, or regulations including those administered by local agencies under the Shoreline Management Act of 1971.

Signed

Assistant Director

Department of Ecology

|   |  | Type  Fermit No.  Date rec'd  Date Issued  Date Expired  New  Rene  DOE Drainage Basin                     | wal   |
|---|--|--|---|
| PARTMENT OF ECOLOGY ate of Washington   |  | Expired Fermit No Advertising needed   |   |
|   | reby made for a permit to dischapter 90.48 RCW and Chapter 372   |  | ate waters  |
| Name of Company   | Alaskan Copper Works   |  |   |
| Mailing Address_  | 1.0. Box 3546, Sentite,  | ultin to pilst   | 1   |
| Location of Plant   | Discharging Waste if Different   | From Above   | 253   |
| 3200 6th Aven   | ue South, Seattle  | PhoneA 3-58  | <u>eo (</u>   |
| Specific Type of  | Industry Metal Fabrication   | ) f)   | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1                         |
| Name of Waterway I  | Receiving Waste Discherge No.  | icinal inwer   |   |
| Location of Indust  | rial Waste Discharge Point (s)   |  |   |
| Raw Water Supply:   | Source City Water Volum  | me_15,000 to 20,000 <b>G</b> a   | ıllons/Day  |
| Raw Water Supply: Authorization For Other   | Source City Water Volum  | me_15,000 to 20,000 <b>G</b> a   | ıllons/Day  |
| Raw Water Supply: Authorization For Other (Specify)   | Source City Water Volum  | ne 15,000 - 0.000Ga Public Supply  | allons/Day Yes  |
| Raw Water Supply: Authorization For Other (Specify) Waste Discharge Vo  | Source City Noter Volum<br>Use: Recorded Right No.   | ne 15,000 - 0.000Ga Public Supply  | Yes   |
| Raw Water Supply: Authorization For Other (Specify) Waste Discharge Vo  | Source City Water Volum Use: Recorded Right No.  lumes: Average Gallons/Da   | Public Supply  Maximum Ga  | Yes   |
| Raw Water Supply: Authorization For Other (Specify) Waste Discharge Vo  | Source City Nater Volumes: Recorded Right No.  lumes: Average Gallons/Da   | Public Supply  Maximum Ga  | Yes  Colling the  |
| Raw Water Supply: Authorization For Other (Specify) Waste Discharge Vo Industrial Pr Cooling  | Source City Water Volum Use: Recorded Right No.  lumes: Average Gallons/Da occasing 15,000  Cooling water is used a compresser.            | Public Supply  Maximum Ga  20,000  rinse water riter of Employees  | Yes  Colling the  |
| Raw Water Supply: Authorization For Other (Specify) Waste Discharge Vo Industrial Pr Cooling Plant Operation:                                     | Source City Water Volumes: Recorded Right No.  lumes: Average Gallons/Dacessing 15,000  Cooling water is used a compressor.  Days per Year | Public Supply  Public Supply  Maximum Ga  20,000  Tinse water, riter of Employees  Day  Night              | Yes  colling the per Shift                                    |
| Raw Water Supply: Authorization For Other (Specify) Waste Discharge Vo Industrial Pr Cooling Plant Operation: Average Maximum                     | SourceCity Water Volumes: Recorded Right No  | Public Supply  Maximum Ga  10.000  Linse water, liter of Employees  Day Night                              | Yes  colling the per Shift Swing 30                           |
| Raw Water Supply: Authorization For Other (Specify) Waste Discharge Vo Industrial Pr Cooling Plant Operation: Average Maximum                     | SourceCity WaterVolumes: Recorded Right No   | Public Supply  Public Supply  Maximum Ga  30,000  rinse water, ster of  Number of Employees  Day Night  45 | Allons/Day Yes  Allons/Day  Colling the per Shift Swing 30 35 |
| Raw Water Supply: Authorization For Other (Specify) Waste Discharge Vo Industrial Pr Cooling Plant Operation: Average Maximum Raw Materials and 6 | Source City Water Volumes: Recorded Right No   | Public Supply  Public Supply  Maximum Ga  20,000  Iinse water, ster o  Number of Employees  Day Night  45  | Allons/Day Yes  Clions/Day  Colling the per Shift Swing 30 35 |

Pene 2

| n til ski  |  | and the second s |  | Para a   |
|--|--|--|--|--|
|  | Item   |  | Average  | Maximum  |
|  | Metal Fabrication  |  | 10,000 lbs.  | 12,000 lb  |
|  |  |  |  |  |
|  | grade data :   |  |  | , , , , , , , , , , , , , , , , , , ,  |
|  |  |  |  |  |
| •  | Sanitary Wastes: Treatment _   | None   | Discharged to Win  | icioal Sewe:   |
|  | Explain any seasonal variation materials and chemicals used work is unredictable or  | in processes, a  | end/or production: Our   | volume of  |
|  | Our customers are varied   |  |  |  |
|  | of the United States.  |  |  |  |
|  | information with your applicat   |  |  | and the first that the first the first that the fir |
| d<br>*   | Describe in detail the physical ischarged into state waters. Inscharged into state waters. Inallytical methods used to dereith your application as Exhibations of the secribe any additions  | Include in the rive this informate 2.  | is description the sam<br>mation. Submit this i<br>changes in waste disp   | pling and<br>nformation  |
| e s  | discharged into state waters. Enalytical methods used to dereith your application as Exhibitional Exhibition and additional application or have under exhibit 3. Include all informing or comments you feel necessary as part of the comments of the end of t | Include in the rive this information or construction serios Exhibit 3. Allessay to clarif  | is description the sammation. Submit this in changes in waste disposal this informations questions, where a so include any additional this application with  | pling and aformation osal methods ion as additional nal informath Exhibit 3.   |
| d<br>F<br>F<br>S<br>S<br>t   | discharged into state waters. Enalytical methods used to dereith your application as Exhibitional Exhibitions are planning or have under Exhibit 3. Include all informapace is necessary as part of  | Include in the rive this information or construction serios Exhibit 3. Allessay to clarif  | is description the sammation. Submit this in changes in waste disposal this informations questions, where a so include any additional this application with  | pling and aformation osal methods ion as additional nal informath Exhibit 3.   |
| E TE SE TE S | discharged into state waters. Inalytical methods used to dereith your application as Exhibitional Exhibition are planning or have underexhibit 3. Include all informing are part of the comments you feel necessary as part of the comments of | Include in the rive this information or construction serios Exhibit 3. Allessay to clarif  | is description the sammation. Submit this in changes in waste disposal this informations questions, where a so include any additional this application with  | pling and aformation osal methods ion as additional nal informath Exhibit 3.   |
| E Y E S t  | discharged into state waters. Inalytical methods used to dereith your application as Exhibitional Exhibition are planning or have underexhibit 3. Include all informing are part of the comments you feel necessary as part of the comments of | Include in the rive this information or construction serios Exhibit 3. Allessay to clarif  | changes in waste disposant this in changes in waste disposant this informations questions, where a so include any addition fy this application with the sand accurate to Signature  W. A. Meacham  | pling and aformation osal methods ion as additional nal informath Exhibit 3.   |
| E Y E S t  | discharged into state waters. Inalytical methods used to dereith your application as Exhibitional Exhibition are planning or have underexhibit 3. Include all informing are part of the comments you feel necessary as part of the comments of | Include in the rive this information or construction serios Exhibit 3. Allessay to clarif  | changes in waste disposant this in changes in waste disposant this informations questions, where a so include any addition by this application with the same accurate to the same | pling and aformation osal methods ion as additional hal informath Exhibit 3.   |
| E Y E S t  | discharged into state waters. Inalytical methods used to dereith your application as Exhibitional Exhibition are planning or have underexhibit 3. Include all informing are part of the comments you feel necessary as part of the comments of | Include in the rive this information or construction serios Exhibit 3. Allessay to clarif  | changes in waste dispusively this informations questions, where as include any addition fy this application with this and accurate to Signature  W. A. Meacham  Printed  | pling and aformation osal methods ion as additional nal informath Exhibit 3.   |

\*Plasse specify units. For example: Toos per day, rounds per day, barrels per day.



Telephone **623-5**800 'ANY 910-**538-**2095 'Yelex 032-318

#### PARRICATORS OF CORROSION-RESISTED METALS

P.O.Box 3846
3660 E. Marginal Way S
Seattle, Washington 90126

### Exhibit No. 1

N. The chemical treatment of stainless steel in this plant is limited to two processes, the major one is passivating and pickling in one solution. The minor one is cleaning stainless steel prior to welding.

# 1. Passivating and oickling:

Accomplished by dipping stainless steel in a solution of nitric acid of approximately 120 degrees F. From time to time an analysis is made for the determination of Nitric Acid concentration. This concentration varies from 200± grams per liter to 50± grams per liter. We are unable to have the ammonium bifluoride determined, our laboratory friends tell us it is not possible to make this determination. The ammonium bifluoride is not active unless in contact with stainless steel. Our controls are most casual, when the passivation is not satisfactory we add nitric acid, when the pickling action requires m re ammonium bifluoride we add more.

After dipping in the above solution the stainless steel is dipped in a tank of water for rinsing, or hosed down with water. The water in the rinse tank is a continuous supply, that has been first used as cooling water in the air compresser.

From the rinsing operation the water runs, on the floor, to a sump. This sump is designed so that all the water must cass thru a bed of limestone on its way to the sewer. The sump contains four hundred pounds of limestone for neutralizing any acid that may be in the rinse water. Metro recently made a check analysis of our effluent, a copy of which is attached hereto.

### Exhibit No. 1

# 2. Cleaning:

Accomplished by dipping stainless steel in a solution composed of Oakite Stripper R6 (6 to 8 oz. per gallon) and Oakite Acalaid (1 part Acalaid to 20 parts Oakite Stripper R-6) at a temperature of 150 degrees F. to 160 degrees F.

After dipping, the parts are removed from the spin and rinsed with water, the rinse water runs on the illoor to the leviously described sump, and then to the sewer.

As described by the Oakite Company, the Oakite regrietory products are as follows:

"Oakite Stripper R6: composed of alkalis, wetting agents, and glucomates."

"Oakite Acalaid: composed of aromatic hydrocar one and wetting agents."

November 18, 1971

To:

G. D. Farcis

A. b. Poole

From:

D. A. Hilderbrand

Subject:

Alaskan Copper Forks (3500 E. Marqueal Ney S. and

3200 6th Ave. S.) pH and Retal Surveys

On November 2nd I ran a pli and metal curvey on Alaskan Copper's rinsevator from their flast Parginel dy plant and I did the same for their 6th avenue south plant on the vertex 4th. The results are attached. Both plants are set to identically with rinsevators from their nitric hydrofluoric soid tank going through a line bed. Each site was sampled at the point where neutralized rinse waters enter the sewer. Neither location appears to have a problem.

DAH: mb

| 11/2/71  | 11/4/      | 71            |
|--|------------|---------------|
| East Harginal Way  | 6th Avenue |               |
| Time pH  | Time       | pli           |
|  |            | 4             |
| 9:25 6.2   | 9:05       | 5.7           |
| 9:40 6.4   | 9:20       | 6.0           |
| 9:55 6.4   | 9:35       | 6.2           |
| 10:10 6.5  | 9:50       | 6.3           |
| 10:25 6.5  | 10:05      | 5.1.          |
| L0:40 6.5%   | 10:20      | 6.0           |
| 10:55 675  | 10:35      | 6.1           |
| 11:10 G.C  | 10:50      | 6.3           |
| 11:25 6.6  | 11:05      | 6.4           |
| 11:40 6.5  | 1.1:20     | 9.4           |
| 11:55 6.3  | 11:35      | 9.2           |
| 12:10 6.3  | 11:50      | 9.1           |
| 12:25 €.3  | 12:05      | 9.4           |
| 12:40 6.3  | 12:20      | 9.1           |
| 12:55 6.4  | 12:35      | 9.8           |
| 13:106.5   | 12:50      | 9.3           |
| 13:25 <b>6.</b> 5  | 13:05      | 8.6           |
| 13:40 6.5  | 13:20      | 8.3           |
| 13:55 6.5  |            | ુδ <b>.</b> 3 |
| 14:10 6.6  | 13:50      | 8.2           |
| 14:25 6.6  | 14:05      | 8.2           |
| 14:40 6.6  | 14:20      | 8.1           |
| 어디에 있다는 경우 그 있는 사람들은 사람들이 되었다면 그렇게 |            |               |
|  | 14:35      | 8.1           |
| 15:00 5.2  | 14:50      | 8.2           |

#### Motals in Parts Per Million

|                | Chrome     | Copper Nicke | 1 Lead | Zinc |
|----------------|------------|--------------|--------|------|
|                |            |              |        | 7.0  |
| 11:40 11/2/71  | 0.50       | 1.42         | 0.22   | 0.82 |
| +14:55 11/2/71 | . 0.88     | 1.01 0.92    | 0.10   | 0.56 |
| Composite 11/2 | /71 * 0.40 | 0.87 0.66    | 0.18   | 0.42 |
| Composite 11/4 | /71 0.18   | 0.18 <0.05   | <0.10  | 0.05 |